



Duct connections / Raccordement des conduits



Balancing chart / Tableau d'équilibrage



| Pressure / Pression | | Fresh air / Air frais | | Stale air / Air vicié | |
|-----------------------|----------------|-----------------------|-----|-----------------------|-----|
| IN. W.G. PO. d'eau | Pascal (Pa) | CFM PCM | L/s | CFM PCM | L/s |
| 0.44 | 110 | 209 | 99 | - | - |
| 0.42 | 105 | 203 | 96 | - | - |
| 0.40 | 100 | 198 | 93 | 207 | 98 |
| 0.38 | 95 | 192 | 91 | 201 | 95 |
| 0.36 | 90 | 185 | 87 | 195 | 92 |
| 0.34 | 85 | 178 | 84 | 189 | 89 |
| 0.32 | 80 | 172 | 81 | 183 | 86 |
| 0.30 | 75 | 164 | 77 | 176 | 83 |
| 0.28 | 70 | 157 | 74 | 169 | 80 |
| 0.26 | 65 | 149 | 70 | 161 | 76 |
| 0.24 | 60 | 141 | 67 | 153 | 72 |
| 0.22 | 55 | 133 | 63 | 145 | 68 |
| 0.20 | 50 | 124 | 59 | 136 | 64 |
| 0.18 | 45 | 115 | 54 | 127 | 60 |
| 0.16 | 40 | 106 | 50 | 117 | 55 |
| 0.14 | 35 | 96 | 45 | 107 | 50 |
| 0.12 | 30 | 87 | 41 | 97 | 46 |
| 0.10 | 25 | 77 | 36 | 86 | 41 |
| 0.08 | 20 | 66 | 31 | 75 | 35 |
| 0.06 | 15 | 56 | 26 | 64 | 30 |
| 0.04 | 10 | 45 | 21 | 52 | 25 |



WARNING

ELECTRICAL SHOCK HAZARD

Could result in serious injury or death

Disconnect power supply
before servicing this equipment



AVERTISSEMENT

RISQUE D'ÉLECTROCUTION

Pourrait entraîner des blessures graves ou la mort

Débrancher le cordon d'alimentation
avant l'entretien de cet appareil