



Duct connections / Raccordement des conduits



Balancing chart / Tableau d'équilibrage



Pressure / Pression		Fresh air / Air frais		Stale air / Air vicié	
IN. W.G. PO. d'eau	Pascal (Pa)	CFM PCM	L/s	CFM PCM	L/s
0.66	164	154	73	163	77
0.63	157	151	71	160	76
0.60	149	147	69	156	74
0.57	142	143	67	152	72
0.54	135	138	65	148	70
0.51	127	133	63	143	67
0.48	120	128	60	138	65
0.45	112	123	58	133	63
0.42	105	117	55	128	60
0.39	97	112	53	122	58
0.36	90	106	50	116	55
0.33	82	99	47	110	52
0.30	75	93	44	104	49
0.27	67	86	41	97	46
0.24	60	78	37	90	42
0.21	52	71	34	83	39
0.18	45	63	30	75	35
0.15	37	55	26	67	32
0.12	30	47	22	59	28
0.09	22	39	18	51	24
0.06	15	30	14	42	20



WARNING

ELECTRICAL SHOCK HAZARD

Could result in serious injury or death

Disconnect power supply
before servicing this equipment



AVERTISSEMENT

RISQUE D'ÉLECTROCUTION

Pourrait entraîner des blessures graves ou la mort

Débrancher le cordon d'alimentation
avant l'entretien de cet appareil